

PRADEEP.D.K

BE(Civil),FIV,MIE

Consulting Engineer/ Approved Valuer
'SWARNAMBA'

Post: Gujjady -576247

Kundapur Tq UDUPI.

Phone: 08254-275865

9448502110

Ref: PDK/SC/010/2021-22

Date: 17.04.2021

BUILDING STABILITY CERTIFICATE

Based on the personal inspection, actual observation and verification of particulars produced, Stability Assessment Report of the school building under the name & style "**Sri Mookambika Public School**" have been prepared & furnished as following.

1. DISCRIPTION OF THE PROPERTY

Name Of The School : "**Sri Mookambika School**"
Building/ Organisation

Name Of the Owner : M/s His Holiness Sri Jayendra
Saraswathi Golden Jubilee Charitable
Trust.

Location of the Building : Sy No. 334/1, 334/2 & 336
At: Yalooru
Golihole Village,
Byndoor Talluk , Udupi Dist.

Date Of Visit : 14.04.2021

Person accompanied at the : Mr.Sampath Shetty
time of inspection Accountant,
Sri Mookambika Public School,
Yalooru



Documents Verified : 1. Architectural Drawing Details
2. Tax Paid Receipts

2. BUILDING DETAILS:

Type Of Structure : RCC Framed Structure
Year Of Construction : 2007-08
Quality of Construction : Moderate
Details of Construction : The building is of RCC framed structure, where symmetry and simplicity being the tone of construction.

Building is **constructed** with following specifications.

RCC Footing, Columns, Plinth beam, Beams, Staircase, Lintels, Slab, Laterate masonry for panel and partition walls, cement plastering for internal walls. Rough cast plaster for External wall, Jack/Honne Wooden frame commercial flush/paneled shutters for door, Vitrified/Ceramic flooring, Toilets with good sanitary system, adequate water supply and electrification.

Class of Construction : Moderate
Total Plinth Area : **12200.00 Sq Ft**
No Of Floors : Ground & First Floor

Residual Age : Another 40 Years
(If properly maintained)

CONCLUSION:

As per the details furnished and physical inspection of the building, it is found that as on date, building is structurally safe & stable enough to take the designed load.

As on date, building is stable And suitable to occupy.

DECLARATION:

- The property was inspected by the undersigned on 14.04.2021
- The undersigned does not have any direct/indirect interest in the above property.
- The information furnished herein is true and correct to the best of my knowledge.

ISSUED WITHOUT PREJUDICE


(PRADEEP D.K.) BE, FIV, MIE
Approved Valuer
Building Planning, Estimation & Valuation
Consulting Engineer / Approved Valuer
8/7 B, 276/147, Kundapura Taluk, Udupi.
Mob. : 9448502110




Pradeep D.K. BE, FIV, MIE
Consulting Engineer / Approved Valuer
Building Planning, Estimation, Valuation
Gujjady-576 247, Kundapura Taluk, Udupi.
Mob. : 9448502110




Pradeep D.K. BE, FIV, MIE
Consulting Engineer / Approved Valuer
Building Planning, Estimation, Valuation
Gujjady-576 247, Kundapura Taluk, Udupi.
Mob : 9448593119